



SUPPLIER QUALITY ASSURANCE REQUIREMENTS (SQARs)

SQAR-02 – Processor/Service

QA-10 FOD CLEANLINESS PROGRAM REQUIRED-FOR FOD CRITICAL PARTS

Parts received must be free of foreign object debris or contaminants anywhere on the product. Supplier must establish a FOD/FOE program at their facility.

QA-16 100% INSPECTION REQUIRED FOR ALL PARTS

Senseker Engineering requires that all parts must be 100% visually inspected for cosmetic defects, scratches, blisters, FOD, or other damage.

QA-21 QUALIFIED PERSONNEL FOR SPECIAL PROCESSES

Personnel performing special processes (i.e., soldering, plating, etc.) must be currently trained or certified to the applicable standards.

QA-25 WORKMANSHIP STANDARDS

Quality workmanship shall be in accordance with applicable drawings and specifications and/or if not identified, with J-STD-001 or American National Standards Institute (ANSI) criteria. Soldering workmanship shall conform to IPC-A-610 (class 2 or 3) as specified.