



SUPPLIER QUALITY ASSURANCE REQUIREMENTS (SQARs)

SQAR-03 – Electronics

QA-10 FOD CLEANLINESS PROGRAM REQUIRED-FOR FOD CRITICAL PARTS

Parts received must be free of foreign object debris or contaminants anywhere on the product. Supplier must establish a FOD/FOE program at their facility.