



## SUPPLIER QUALITY ASSURANCE REQUIREMENTS (SQARs)

### SQAR-04 - Raw Material/Metals

#### **QA-03 RAW MATERIAL TRACEABILITY**

All items manufactured under this purchase order shall be traceable to raw material used. Traceability and inspection records shall be available upon request by Senseeker Engineering. Identification of raw material used shall include, as applicable, but not limited to, the following type of information: lot number, material type, specification, heat number, etc. In any case, supplier shall adequately identify all material in such a manner that full traceability of raw material used is included.

Note: Supplier must include lot numbers of material supplied to the vendor (subcontracted items) as specified in the purchase order.

#### **QA-04 DFARS COMPLIANCE REQUIRED (*WHEN SPECIFIED*)**

Product must comply with DFARS 252.225-7009 - preference for domestic specialty metals. Melted in USA or qualifying country.